

FRAME, Angle

Do. in peaks ...

Do. in way of I

2500,12,19.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel S.S. "BEATTY ROSE".

Report

Gls.

No. 40370

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required, and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the vessel, so that the Classing Committee may have all the salient points presented in the endorsement." — Extract from Sub-Committee's Report, 1903.

Nature of Survey

When due

100 A.l. (Steel)

1 Dk. (Steel) "Well Dk."

Cell DBf 136' 215t. FPT 80t. APT 34t.

FK. 3 BH. Cem. Lloyd's A.& C.P. Q108', B15', F28'.

Machinery aft.



©2021
23.9.20

Lloyd's Register
Foundation

BEAMS, Up