









GENERAL REMARKS—(continued).

PARTICULARS FOR RECORD in the REGISTER BOOK.—Length of Poop ☒ ft., R.Q.D. 116.0 ft., Bridge 9.16 ft., Forecastle 23.52 ft. (in feet and tenths). When the Poop is joined to the B.D., this should be distinctly stated.

No. and Material of Decks (if Iron or Steel) and whether wholly or partially covered with wood, and No. of tiers of Beams (this information is to be given as should appear in the Register Book) 1 D<sup>th</sup> (S<sup>th</sup>)

Official No. ; Signal Letters State if Machinery is fitted aft ☒ yes  
How are the surfaces preserved from oxidation? Inside Paint & cement  
The underside of the tank top plating is not coated Outside Paint

PARTICULARS OF WATER BALLAST.—State whether the Double bottom is constructed on the cellular system or with girders on floors ☒ yes

Where Fitted.	Length. Feet.	Water Capacity. Tons.	Where Fitted.	Length. Feet.	Water Capacity. Tons.
Double bottom, aft,			Fore peak tank,		
Double bottom, under Engines and Boilers,			After peak tank,		
Double bottom, if under Engines only,			Deep tank, aft,		
Double bottom, if under Boilers only,			Deep tank, forward,		
Double bottom, forward,	111.10	162	Other tanks, if fitted,		
	Total capacity of double bottom	162	(If necessary, furnish further information by sketch.)		

\* The wells are not to be included in the lengths of the tanks.

State whether the above have been tested as required by the Rules. ☒ yes

Order for Special Survey No.

Date

No. 237 in builder's yard.

Dates of Surveys held while building

1919:— Feb 14. 26. Mar 6. April 3. 11. 28. May 2. 10. 24. June 6. 12. 20. July 10. 25. Aug 22. Sep 5. 22. Oct 13. 27. Nov 6. 20. Dec 8. 1920:— Jan 6. 16. Feb 2. 16. Mar 11. 27. Apr 19. May 7. 21. 31. June 11. 22. 29. July 16. 20. 30. Aug 19. Sep 13. 24

Total No. of Visits 42

Surveyor's Signature

Thomas S. Shupe