

W43B

F.E.

Received by Chief Ship Surveyor 20-11-16

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S. S. Westwick

Rpt. Sld

No. 26846

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 21/5/92.)

Transverse No. 78.5

Depth "d" 22.92

Framing: Table No. 3 page 16

Description Bullt Angles

Longitudinal No. 31792

Proportions Length = 11.73  
Depth =

Deck Sheerstrake as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\boxtimes$  100 A.1. (Steel) "Skelter Deck with freeboard," as recommended. The Summer freeboard of 9' 2 1/2" from centre of disc to top of statutory deck line at Skelter deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

W714-0093

$\boxtimes$  100 A.1. (Steel) "Skelter DK" with freeboard.

1 DK (Steel) and Skelter DK (Steel)

Cell DB a 134', u E 26', f 176' 1165t, FPT 49t, APT 106t.

FK. GBH. Com. Lloyds A.S.C.P.



© 2021 Lloyd's Register Foundation

BEAN  
BEAN