

3m.4.18.

Wreck Bay 43 B.

W731-0046

Received by Chief Ship Surveyor

15. 8. 18

Received from Chief Ship Surveyor

19 AUG 1918

VESSEL'S NAME

SS Wellingtonia

Rpt.

By

No.

16840

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Ship Committee's Report, 24/5/92.)

Nature of Survey

Damage

The Gibraltar Surveyor reported in March last this vessel had sustained damage to shell plating, frames, bulwarks, etc. through being fouled by another vessel, and the Surveyor recommended repairs be carried out within a reasonable time.

The Barry Surveyors now report the vessel has been examined in dry dock, after grounding.

The bottom has been cleaned & coated.

No damage found on bottom.

Riveting & Caulking in part of Damage referred to above overhauls. It is submitted the vessel appears worthy to remain as

classed, with fresh record of survey, subject as above.

100 A.1.

8. 18

By [Signature] subjt. etc.

16. 8. 18



© 2021

Lloyd's Register Foundation

Survey 8-18.