

Received by Chief Ship Surveyor 12-2-18

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Shells Wellingtonia Rpt. Inv No. 70672

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 72-34 Depth "d" 21.29  
 Framing: Table No. ✓ Description Corrugated sides, as approved  
 Longitudinal No. 23944  
 Proportions Length = 10.49  
 Depth =  
Bridge Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  100 A-1 (Shell) as recommended, with notation of

Corrugated sides

1. Deck (Shell) & Webframes.

Cell DB 284 673E. F.P.T. 145E A.P.T. 1565

E.K. 6 BH. Am. Lids as per. P29. B98' F32'

© 2021 44.2.18



Lloyd's Register  
Foundation

W431-0049

To  
Mr White