

F.E.

*Received from Chief Ship Surveyor*

L'S NAME

*Rpt.*

No.

(<sup>a</sup>The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.)—*Extract from Sub-Committee's Report, 24/5/92.*)

ansverse No.

Depth, "d"

aming: Table No.

Description

ngitudinal No.

Proportions  $\frac{\text{Length}}{\text{Depth}} =$ 

Deck Sheerstrake

The Glasgow Surveyors Report that the Survey has been completed.

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed *100 A. 1. (Steel)* as recommended.


✓ 100 A-1 (St.)

1 5th (St) Wm on.

HP 3P7 40t aryl 2t

JK 3BH. "Cm" Lloyd a 161 Q46 B7 F25.

May 2020


 Lloyd's Register  
 Foundation