

10777-0016

F.E.

Ship Surveyor *J. 2. 14*

Received from Chief Ship Surveyor

NAME *SH 75 (oil engine) Sebastian* Rpt. *Dim* No. *7817*

Requests of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.

Erse No. *71.25* Depth "d" *16.33*
 g: Table No. *✓* Description *Bulk angles & Net frames*
 udinal No. *22087*
 Proportions Length = *11.81*
 Depth =
 Deck Sheerstrake *As per Rule.*

This vessel appears to have been built in accordance with the and the approved plans, and it is submitted she is eligible to

Assessed *÷ 100 A.1. (Stub) "Carrying Petroleum in bulk"*

Recommended.

÷ 100 A.1 (Stub) "Carrying Petroleum in bulk"

2 Sts (Dth) & Net frames

N.B. Hull L.P. & 43' 8" L. 22' 1" 7778 AR 1680

F.K. 13 BH. L.P. Lays a & C.P.

Date of Build 2-14

2020
P70, B27 F34
McKay Agt
W.H.W.
J. 2. 14