

WB=CellDBorDBa
 total capacity _____ tons. FPT _____ tons; APT _____ tons; MT _____ feet _____ tons.)
 N.B.—All alterations in the existing records should be underlined.
 If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside

CHARACTER.
 * for Special Survey.
 Date of last Survey and of

in, 10, 15.

WRECK BOX
 No. 18 Wreck 18

1

7 APR 1916

Received by Chief Ship Surveyor 12.4.16

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "Harrovia" Rpt. HyR No. 12549

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey DAMAGE.

Damage through heavy weather

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str.	Plates	Dk.	Plates
Renewed									
Removed and faired } or repaired..... }									
Faired or repaired } in place..... }									

Other items:-
 Vessel examined in dry dock. Bottom coated.
 A number of rivets renewed in keel & A & B
 Strakes in way of No 1 tank & some renewed in
 Centre keelson, tank side brackets etc.
 Minor repairs effected.

It is submitted the vessel is worthy to remain as classed with
 record of Survey B16 as recommended

100 A.1. Skelton dr with fbd.
B16 HyR.

© 2020
 Lloyd's Register
 Foundation
 W864-0027