

3m, 8, 17.

Wreck Box 20

Received by Chief Ship Surveyor 30.11.17

Received from Chief Ship Surveyor 1 DEC 1917

VESSEL'S NAME

Sheels Drington Court

Rpt.

By

No.

16457

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The notation carrying oil fuel F.P. above 150°F  
in double bottom tanks, should remain in Col 3, until  
the bellmouths have been fitted to the suction &  
the tanks tested to the top of the filling pipes.



© 2021

30.11.17  
Lloyd's Register  
Foundation

W873-0036