

3m, 3, 13.

WRECK BOX

No.

17

RETAIN

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Nord J. Gustiana

Rpt.

End

No.

2954

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

This wood vessel appears to have been built in accordance with the Rules and the approved plan, and it is submitted she is eligible to be classed 13A1 ("Wood") as recommended, viz:—

See Table A.

- 10 years for Material
- 1 year for Mixed Materials
- 1 year for Salting
- 1 year for Metal Fastenings

13A1 "Wood" 10 & 12 years mat. "cf", Salted

RYM 4.13. Lloyd's A + C.P.

W.

M.



13. 6. 13

© 2021

Lloyd's Register Foundation

W883 - 0116