

F.E.

by Chief Ship Surveyor 6/6/11

Received from Chief Ship Surveyor _____

SHIP'S NAME Stl. S.S. "Grangemoor" Rpt. Sld. No. 74862

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 71.95 Depth "d" 21.46

Plating: Table No. 3 page 11 Description Bull angle as approved.

Longitudinal No. 23790

Proportions Length = 10.48
Depth = _____

Bridge Deck Sheerstrake and strake below in one strake of approved thickness.

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed **✠ 100A1 ("Steel")** as recommended.

✠ 100A1 ("Steel")

1 Dk (Stl.)

WB=cell DBa 112' x E 74' f 132' 698t. A.P.T. 202t.

FK. 5 BH. sem. Lloyds A+C.P. P. 76' B 95' F 30'

RA
2020

Lloyd's Register
W907-0028
Foundation