

Less C
Less a
Eng
TONNA

Im. 12.15.

F.E.

Received by Chief Ship Surveyor 29. 11. 16

Received from Chief Ship Surveyor

VESSEL'S NAME Sheels Carnarthen Rpt. Hpl No. 15315

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 78.074 Depth "d" 23.75

Framing: Table No. 3 page 16 Description Bull Angle as approved

Longitudinal No. 29655

Proportions Length = 10.78
Depth

Bridge Deck Sheerstrake as per Rule.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed * 100 A.1 (Steel) as recommended.

* 100 A.1 (Steel)

1 DK. (Steel)

Cell DB 336 1099E. F.P.T. 102E A.P.T 94E

FK 6 BH. Cam. Lloyd's Reg. Proj. B 240 F 36'

[Handwritten signature]
29. 11. 16



© 2021

Lloyd's Register Foundation
1926-0208

BEAN