

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Stl. Sc. motor tanker "W.B. WALKER" Rpt. Ham No. 21578

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/2.)

1st Long. No. 17945

Depth "d" -

2nd Long. No. 50925

Proportions =  $\frac{L}{D}$  13.10

Framing as approved

Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

100A1 Carrying petroleum in bulk

2 Dks "Longitudinal Framing" "Bracketless System"

Cell DBuE 85' 184t, DTf 30' 990t, FPT 323t, AFTs 240t

FK, 16 EH (12 EH to U Dk 4 EH to 2nd Dk), Lloyd's A & CP

P 107', B 34', F 51'

Rudder electrically welded

Machy. aft

*Handwritten signature/initials in a circle*

*Handwritten date: 12.7.20*



© 2020

Lloyd's Register Foundation

*Handwritten number: W93-0035*