

Tonnage  
Space

8500.44  
16.47

Depth "d" at middle of length See Secs. 2 & 13....  
(when no 3rd deck)

13.42  
19.12

Managers

g. Book.)

ONE No. 610.



# Lloyd's Register of Shipping.

Ocean Chambers, Lowgate,

LLOYD'S REGISTER  
LONDON.

Hull, 5th. January, 1917.

REC'D JAN 10 1917  
ANS'D 9

Dear Sir,

In reply to your letter of the 4th. instant, regarding the 1st. Entry report on the S. S. "CONDESA", I beg to state that the cast iron coaling scuttles are fitted on the bridge deck as shewn amended on the report and that coamings and hatches are fitted to the bunker openings on the Shelter Deck.

I am, Dear Sir,

Yours faithfully,

*W. R. M. Aspinall*

The Secretary,

LONDON. E.C.

*writing necessary in connection of classification.*



© 2020  
W933-0106

Lloyd's Register  
Foundation

W933-0108

Referred to the Chief Ship Surveyor.

CRD

JAN 6 1917

~~J. B. Rye~~  
6-1-17

RECEIVED

NAVY DEPARTMENT

ADAMS REGISTER

I am, Dear Sir,

in reply to your letter of the 27th inst.

concerning the liability of the vessel for the cargo loss. I am sorry to hear that the cargo was damaged and that the vessel was damaged. I am sorry to hear that the cargo was damaged and that the vessel was damaged.

I am, Dear Sir,

Yours faithfully,

Wm. Adams



© 2020

Lloyd's Register Foundation