

3m, 12, 16.

Wreck 5-

WRECK BOX

No.

5 top

5 APR 1917

Received by Chief Ship Surveyor 4. 4. 17

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. S.S. "BEEMAH".

Rpt. B.B1. No. 152

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

Repairs

The class of this vessel is subject to the 5th gudgeon from the bottom (repaired by oxy-acetylene Process at Barry in September last), being specially examined at the next dry docking.


The Bahia Blanca Surveyor now reports the vessel has been examined afloat and a few rivets renewed.

It is submitted the vessel appears worthy to remain as classed, without fresh record of survey, subject as above.

As now subj. Etc

4. 4. 17

© 2020



Lloyd's Register
Foundation