

Tonnage
Do. between
and 3rd
Total

1300/1072
1

W. B. T.

Sent to Chief Surveyors 28.12.17

Received from Chief Surveyors

VESSEL'S NAME *Sheela Ardgarthock*

Report *Sub*

No. 17225

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

Nature of Survey

When due

❖ 100 A-1 (Steel)
1 DK (Steel) in web frames. Well Dr
Cell DB + 121 2316. F.P.T. 606 A.P.T. 496
F.K. 36H. Cam. Laps. axed. Q III. F26. Mchly aft

The Certificate of Classification to be a
Cargo battens not fitted. and this should
be noted to be printed in the Register.

MA
29.12.17

BEAMS