

Chief Surveyors _____

Received from Chief Surveyors _____

NAME _____

KALLIOPI S.

Report _____

Bal

No. *6992*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

of Survey _____

Damage

When due _____

*Subject to No 6 shell plate from forward in 5th
strake below sheer (SS) Ew 5.39, being specially examined
at the next dry docking.*

CES

27.3.60

The Certificate of Classification to
be endorsed "*Cargo bulwark not
found*" and the same notation to be
printed in the Register Book.



© 2020

Lloyd's Register
Foundation

1985-0098