

# ANNUAL SURVEYS.

No. 26305 Survey held at Liverpool Date, first Survey Dec 2<sup>nd</sup> Last Survey Dec 4<sup>th</sup> 1878  
 No. in on the Bark "Elissa" Master G. Wheaton.  
 Reg. Book. 342 Tonnage 409 Built at Aberdeen When built 1877 - 10 mo.  
 By whom built A Hall & Co. Owners H. F. Watt.  
 Port belonging to Liverpool Destined Voyage Bahia.  
 If Surveyed Afloat or in Dry Dock Sandon Dry Dock.

Last Survey, No. 20948. Port of Liverpool Classed 100 AI. 5.78.  
 Present Condition of the Decks Good Treenails Rivets. Good  
 Waterways 4 Breasthooks and Stems 4  
 Comings 4 Transoms, Pointers, and Crutches 4  
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4  
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4  
 Planksheers 4 Keelsons 4  
 Sheerstrakes 4 Clamps and Shelves 4  
 Topsides 4 Ceiling 4  
 Wales 4 Rudder 4  
 Plank (Bottom) and Counter 4 Copper or Y.M. Cement When put on 77.  
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Caulking of Bottom, Deck, & Waterways Good  
 Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 Windlass and Capstan Good.  
 Pumps 4  
 Boats 4  
 Masts, Yards, &c. 4  
 Condition, how ascertained from on board.  
 Sails Good  
 Anchors, No. of and  
 Cables and  
 Hawseers and Warps and  
 Standing and Running Rigging Sufficient.  
 General Observations, Opinion as to Class, &c.

Bottom sighted cleaned and coated with paint, and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Dec<sup>r</sup> 24 1878  
 Character assigned 100 AI.

T. Skilston.  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) 18

No. 352 Survey held at Liverpool Date, first Survey Dec 11<sup>th</sup> Last Survey Dec 14<sup>th</sup> 1878  
 No. in on the Bark "Albany" Master Lindsay  
 Reg. Book. 352 Tonnage 499 Built at Dundee When built 1867 - 6 mo.  
 By whom built Brown Owners W. O. Taylor.  
 Port belonging to Dundee Destined Voyage Valparaiso.  
 If Surveyed Afloat or in Dry Dock Clarence Dry Dock.

Last Survey, No. 20180 Port of Liverpool Classed S.S. Nwc No 2.75. 1.78.  
 Present Condition of the Decks Good Treenails Rivets. Good  
 Waterways 4 Breasthooks and Stems 4  
 Comings 4 Transoms, Pointers, and Crutches 4  
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4  
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4  
 Planksheers 4 Keelsons 4  
 Sheerstrakes 4 Clamps and Shelves 4  
 Topsides 4 Ceiling 4  
 Wales 4 Rudder 4  
 Plank (Bottom) and Counter 4 Copper or Y.M. Cement When put on 67.  
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Caulking of Bottom, Deck, & Waterways Good  
 Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 Windlass and Capstan Good.  
 Pumps 4  
 Boats 4  
 Masts, Yards, &c. 4  
 Condition, how ascertained from on board.  
 Sails Good  
 Anchors, No. of and  
 Cables and  
 Hawseers and Warps and  
 Standing and Running Rigging Sufficient.  
 General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and coated with paint, and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Dec<sup>r</sup> 24 1878.  
 Character assigned \* AI

T. Skilston.  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) 18



Phoca  
Alband

26303