

Recd 26/8/79.

ANNUAL SURVEYS.

2438

No. 26638 Survey held at Liverpool Date, first Survey July 21st Last Survey Aug 15th 1879
 No. in on the Iron Ship "Baroda" Master Brown
 Reg. Book. 92 Tonnage 1364 Built at Belfast When built 1864-4
 By whom built Harland Owners J & J Brocklebank
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Afloat in Brunswick dry dock

Last Survey, No. 21424 Port of Liverpool Classed * A 1-9-70
 Present Condition of the Decks Good

Waterways	"	Transoms	Good	Windlass and Capstan	Good & efficient
Comings	"	Breasthooks and Stems	"	Pumps	"
Upper Deck Beams & Fastenings	"	Transoms, Painters, and Crutches	"	Boats	"
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Planksheers	"	Ditto ditto at other places	"	Condition, how ascertained	See from deck
Sheerstrakes	"	Keelsons	"	Sails	Good
Topsides	"	Clamps and Shelves	"	Anchors, No. of	"
Wales	"	Ceiling	"	Cables	"
Plank (Bottom) and Counter	"	Rudder	"	Hawsers and Warps	"
Engine Room Skylights	"	Copper or Y.M. Cens	When put on 64	Standing and Running Rigging	Efficient
Coal Bunker, Openings, Lids, &c.	"	Caulking of Bottom, Deck, & Waterways	Good	Cargo and Main Hatchways	Good
General Observations, Opinion as to Class, &c.					

The bottom scraped and painted - This vessel is now in good condition and in my opinion eligible to remain as Classed

Committee's Minute Liverpool Sep^r 5th 1879
 Character assigned * A 1.

E. S. Meekley
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 353 Survey held at Liverpool Date, first Survey July 23rd Last Survey Aug 15th 1879
 No. in on the Iron Bk "Elissa" Master G. Meaton
 Reg. Book. 353 Tonnage 409 Built at Aberdeen When built 1877-10 mo
 By whom built A. Hall & Co Owners H. J. Watt
 Port belonging to Liverpool Destined Voyage America
 If Surveyed Afloat or in Dry Dock Afloat in Canning dry dock

Last Survey, No. 2236 Port of Liverpool Classed 100 A 1-12-70
 Present Condition of the Decks Good

Waterways	"	Transoms	Good	Windlass and Capstan	Good & efficient
Comings	"	Breasthooks and Stems	"	Pumps	"
Upper Deck Beams & Fastenings	"	Transoms, Painters, and Crutches	"	Boats	"
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Planksheers	"	Ditto ditto at other places	"	Condition, how ascertained	See from deck
Sheerstrakes	"	Keelsons	"	Sails	Good
Topsides	"	Clamps and Shelves	"	Anchors, No. of	"
Wales	"	Ceiling	"	Cables	"
Plank (Bottom) and Counter	"	Rudder	"	Hawsers and Warps	"
Engine Room Skylights	"	Copper or Y.M. Cens	When put on 77	Standing and Running Rigging	Efficient
Coal Bunkers, Openings, Lids, &c.	"	Caulking of Bottom, Deck, & Waterways	Good	Cargo and Main Hatchways	Good
General Observations, Opinion as to Class, &c.					

The bottom scraped and painted - This vessel is now in good condition and in my opinion eligible to remain as Classed

Committee's Minute Liverpool Sep^r 5th 1879
 Character assigned 100 A 1.

E. S. Meekley
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Baroda
Elissa

26638