

Recd 26/8/79.

ANNUAL SURVEYS.

24380

No. 26638 Survey held at Liverpool Date, first Survey July 21st Last Survey Aug 15th 1879
 No. in on the Iron Ship "Baroda" Master Brown
 Reg. Book. 92 Tonnage 1364 Built at Belfast When built 1864-4
 By whom built Harland Owners J & J Brocklebank
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Afloat in Brunswick dry dock

Last Survey, No. 21724 Port of IronClassed * A 3-9-70
Plan No 3-76

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

General Observations, Opinion as to Class, &c.

Tonnage

Breasthooks and Stems

Transoms, Painters, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper or Y.M. Cen When put on 64

Caulking of

Bottom, Deck, & Waterways

When put on 64

Scuppers

Cargo and Main Hatchways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Haulsers and Warps

Standing and Running Rigging

Hatches

The bottom scraped and painted - This vessel is
 now in good condition and in my opinion eligible to
 remain as Classed

Committee's Minute

Character assigned

Liverpool Sep 5th 1879
* A 1.

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. ✓ Survey held at Liverpool Date, first Survey July 23rd Last Survey Aug 15th 1879
 No. in on the Iron B.E. "Elissa" Master G. Meaton
 Reg. Book. 355 Tonnage 409 Built at Aberdeen When built 1877-10 no
 By whom built A. Hall & Co Owners H. J. Watt
 Port belonging to Liverpool Destined Voyage America
 If Surveyed Afloat or in Dry Dock Afloat in Cannery dry dock

Last Survey, No. 2236 Port of IronClassed 100 A 1-12-70

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

General Observations, Opinion as to Class, &c.

Tonnage

Breasthooks and Stems

Transoms, Painters, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper or Y.M. Cen When put on 77

Caulking of

Bottom, Deck, & Waterways

When put on 77

Scuppers

Cargo and Main Hatchways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Haulsers and Warps

Standing and Running Rigging

Hatches

The bottom scraped and painted - This vessel
 is now in good condition and in my opinion eligible
 to remain as Classed

Committee's Minute

Character assigned

Liverpool Sep 5th 1879
100 A 1.

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Baroda
Elissa

26638



© 2018

Lloyd's Register
Foundation