

NAME LIZZIE AND ANNIE

Report GRIMSBY No. 22623

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in $\frac{1}{16}$ of an inch.

KEY.	AMIDSHIP.				FORWARD.				AFT.				REMARKS.				
	Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.			
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.		Std.	Port.	Std.	
STRAKE																	
STRAKE	38 6	6	5	-	1	5½	6				6	6					<p> $\frac{6}{16} = .38$ $\frac{5\frac{1}{2}}{16} = .34$ $\frac{5}{16} = .31$ $\frac{4\frac{1}{2}}{16} = .28$ 4 shell plates renewed on account of small fractures. </p>
W	5	5	5	.	.	6	5				5	4½					
.....	5	4½	5½	½	.	5	5				4½	4½					
.....	5	5	5	-	.	4½	4½				Cement.						
.....	5	Cement				Cement											
.....	5																
.....	6																

Drillings at ends to be made in the vicinity of the peak bulkheads.