

See 4943

17 SEP 1957

Rpt. C 11 (a).

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

118 SEP 1957

REPORT ON ANNUAL LOAD LINE SURVEY

Name of Ship "LIZZIE & ANNIE" ✓ Official Number 76519 ✓ Port of Registry Hull. ✓

Place of Survey Hull. Dates of Survey 10th & 13th Sept. 1957. Date of last Load Line Survey 20th July, 1956.

PARTICULARS OF SURVEY

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
DECKWAYS, INCLUDING SMALL HATCHWAYS.			
Exposed on freeboard deck.			
Coamings, their stays and stiffeners	Good. ✓		
Beams	Good. ✓		
Fore and afters	Good. ✓	except one to repair. ✓	13/9/57. ✓
Covers	Good. ✓		
Tarpaulins	Good. (2). ✓		
(State number per hatchway)			
Seats and battens	Good. ✓		
Lashings and their fittings	Good. (Wire ropes and stretching screws). ✓		
Wedges	Good. (Yes). ✓		
(Is supply, including spares, adequate?)			
Exposed on superstructure decks, including raised quarter decks.			
Coamings, their stays and stiffeners	-		
Beams	-		
Fore and afters	-		
Covers	-		
Tarpaulins	-		
(State number per hatchway)			
Seats and battens	-		
Lashings and their fittings	-		
Wedges	-		
(Is supply, including spares, adequate?)			
In superstructures not intact or not protected by Class I closing appliances.			
Coamings	-		
Beams	-		
Fore and afters	-		
Covers	-		
Tarpaulins	-		
(State number per hatchway)			
Seats and Battens	-		
Lashings	-		
Wedges	-		
(Is supply, including spares, adequate?)			
DOORS IN EXPOSED POSITIONS.			
Exposed below freeboard deck.			
Coamings, their supports and deck connections	Good. ✓		
Lashing arrangements	Good. ✓		
Exposed below decks of superstructure which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	-		
Lashing arrangements	-		
DOORS IN PARTIALLY ENCLOSED SUPERSTRUCTURES.			
Exposed on freeboard and superstructure decks.			
Lashing arrangements	-		
Within partially enclosed superstructures.			
Lashing arrangements	-		
WINERY CASINGS.			
Casing Top.			
Fiddle openings, their covers and fastenings	-		
Skylights, their fastenings, covers and lashings	Good. ✓		
Exposed on freeboard and raised quarter decks.			
Doors and fastenings	Good. ✓		
Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	-		
Within partially enclosed superstructures.			
Doors and fastenings	-		
FLUSH BUNKER SCUTTLES and chain attachments			
	-		
COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	Good. ✓		

* Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Ministry of Transport Circular 1687, paragraph 117 (i)).

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date eff.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPER-STRUCTURE BULKHEADS.			
Forecastle	Good. ✓		
Bridge, fore end	-		
Bridge, after end	-		
Port R.O.D.	No openings. ✓		
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures	-		
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves	Arrangements satisfactory. ✓		
17. SIDE SCUTTLES AND DEADLIGHTS			
18. GUARD RAILS			
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways	-		
20. LIFELINES (fittings and material)			
21. FREEING PORTS.			
Shutters	Good. ✓		
Protection bars	- ✓		
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances	-		
23. ITEMS NOT INCLUDED IN THE FOREGOING.			
24. LOAD LINE MARKS			
		Verified.	

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Ministry of Transport Circular and the requisite details of the survey have been entered herein.

Index Nos. of items examined.† († Insert "all" in case of a complete survey.)	Signature of Surveyor.	Place.	Date.
All.	<i>H. J. Naisby</i>	HULL	13th September

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor *H. J. Naisby* Place HULL. Date 13th Sept

Signature *H. J. Naisby*

Date 16th September, 1957.

Fee £3.

Number of Visits Two.

Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11 should be reported on Form C 11 (contd.) and attached to Form C 11 on the Ship, a copy being forwarded to the Freeboard Department.

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.

LR-FAF-SA13-240

REPORT
m.v. "LL"
Hull

ENCLOSURE

Telegrams: C

Dear

your
a cer
Certi

credi
docum

The S

CASINGS.
op.
openings, their covers a
s, their fastenings, cover
on freeboard and raised
nd fastenings ...
on superstructure deck
s.
nd fastenings ...
artially enclosed superstr
nd fastenings ...
BUNKER SCUTTLES an
IONWAYS, including d
astenings, covers ...
• Tarpaulins, battens