

12 OCT 1948

Encls. Rpt. No. 21893.

LIZZIE & ANNIE Official Number 76519 Port of Registry Hull
Grimsby Dates of Survey 11/10/45 Date of last Load Line Survey 7/11/44

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
CLASSES, INCLUDING SMALL HATCHWAYS.			
on freeboard deck.			
... their stays and stiffeners ...	Good ✓	none	
... ..	Good ✓	none	
... ..	Good ✓	none	
... afters ...	Good ✓	none	
... ..	Good ✓	none	
as ... number per hatchway)	Good 2 per hatchway	none	
battens ...	Good ✓	none	
and their fittings ...	Good ✓	none	
supply, including spares, adequate ?) Yes.	Good ✓	none	
on superstructure decks, including raised or decks.			
their stays and stiffeners ...	None ✓		
... ..	✓		
fters ...	✓		
... ..	✓		
number per hatchway)	✓		
and battens ...	✓		
gs and their fittings ...	✓		
supply, including spares, adequate ?)	✓		
in superstructures not intact or not protected Class I closing appliances.			
gs ...	None ✓		
... ..	✓		
nd afters ...	✓		
... ..	✓		
alins ... ate number per hatchway)	✓		
aud Battens ...	✓		
supply, including spares, adequate ?)	✓		

ns, battens, covers, etc., to be examined in place as well as separately (*see* Board of Trade Circular 1687, paragraph 117 (i)).

T. (MADE IN ENGLAND.)



© 2018

Lloyd's Register
Foundation

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections	Good ✓	none	
Closing arrangements	Good ✓	none	
5. To spaces below decks of superstructures which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	none ✓		
Closing arrangements	✓		
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements	none ✓		
7. Within partially enclosed superstructures.			
Closing arrangements	none ✓		
MACHINERY CASINGS.			
8. Casing Top.			
Fiddle openings, their covers and fastenings	none ✓		
Skylights, their fastenings, covers and lashings	Good ✓	none	
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	Good ✓	none	
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	none ✓		
11. Within partially enclosed superstructures.			
Doors and fastenings	none ✓		
12. FLUSH BUNKER SCUTTLES and chain attachments			
	none ✓		
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	Good ✓	none	

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPERSTRUCTURE BULKHEADS.			
Forecastle	Good ✓	none	
Bridge, fore end... ..	✓		
Bridge, after end	✓		
Poop	✓		
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures	none ✓		
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves	Good ✓	none	
17. SIDE SCUTTLES AND DEADLIGHTS	none		
18. GUARD RAILS	none		
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways	none		
20. LIFELINES (fittings and material)	none ✓		
21. FREEING PORTS			
Shutters	Good ✓	none	
Protection bars	✓		
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances	✓		
23. ITEMS NOT INCLUDED IN THE FOREGOING	✓		
24. LOAD LINE MARKS	Verified and found correct.		

Particulars of any change from the conditions given on the Load Line Certificate on on Form C 11.

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Board of Trade C 11 and the requisite details of the survey have been entered herein.

Index Nos. of items examined. †	Signature of Surveyor.	Place.	Date.
all	G. B. Auk	Grimsby	11 th October 1945

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor G. B. Auk Place Grimsby Date 11th October 1945

Signature G. B. Auk

Date 11th October 1945

† Insert "all" in case of a complete survey.

Fee L1-0-0

Number of Visits one

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.

LR-FAF-5413-289 212

C 11 (a).

REPORT

Name of Ship h.v.

Date of Survey 11

DECKWAYS, INCLUDING

Exposed on freeboard

Coamings, their stays
Beams
Fore and afters
*Covers
*Tarpaulins
(State number per
*Cleats and battens
Lashings and their fittings
Wedges
(Is supply, including

Exposed on superstructure decks.

Coamings, their stays
Beams
Fore and afters
*Covers
*Tarpaulins
(State number per
*Cleats and battens
Lashings and their fittings
Wedges
(Is supply, including

Within superstructures closing appliances.

Coamings
Beams
Fore and afters
Covers
Tarpaulins
(State number per
Cleats and Battens
Wedges
(Is supply, including

OPENINGS IN EXPOSED

spaces below freeboard
Coamings, their supports
Closing arrangements

spaces below decks of
closed by Class I ap
Coamings, their supports
Closing arrangements

spaces below decks of
closed by Class I ap
Coamings, their supports
Closing arrangements

OPENINGS IN EXPOSED

posed on freeboard and s
Closing arrangements

thin partially enclosed s
Closing arrangements

EVERY CASINGS.

ing Top.
dley openings, their cover
lights, their fastenings, c

ed on freeboard and rai
rs and fastenings

ed on superstructure d
decks.
s and fastenings

in partially enclosed super
s and fastenings

OPENINGS IN EXPOSED

OPENINGS, including
ways.
s, fastenings, covers

* Tarpaulins, batter



© 2018
Lloyd's Register
Foundation