

Sent to Chief Surveyor

11.10.94.

Received from Chief Surveyor

VESSEL'S NAME

Im S.S. "Bakuin" Report Ham. No. 3019

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Lloyd's (Completion)

The S.S. No. 2 was partly held in March and August last, and has now been completed, and some minor repairs effected.

100 A1 It is submitted the vessel appears worthy to remain classed "Carrying petroleum in bulk", with record 10, 94, Ham. and notation of S.S. Ham. No. 2-94, as recommended.

100 A1 "Carrying Petroleum
in bulk."

10.94 Ham.
S.S. Ham. No. 2-94

The Surveyor should be requested to state whether the bottom of this vessel is covered with cement or asphalte, in order that the record in the Register Book may be amended, if necessary.

He should also sign his report and return it.



© 2018
11/10/94
Lloyd's Register
Foundation