

110 JUN 1944

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "PAMIR" REPORT Wln. No.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

This barque's class is subject to the shell plating being drilled at the first opportunity.

The WELLINGTON Surveyor reports (3.44) this vessel placed in a floating dock and a considerable part of a S.S. No.2 held (vessel 38 years old) and renewals effected to rigging and all parts of the masts, beams, rigging and running gear placed in good order.

The decks and fore and after main decks have been recaulked and payed.

Minor repairs effected.

IT IS SUBMITTED the vessel be continued as classed with record of docking survey 3.44 subject as above.

3.44 Wln. subject.

*Est 110*  
6.6.44  
S.S. PART HELD.



© 2018

Lloyd's Register  
Foundation