

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

10 JUN 1945

VESSEL'S NAME "PAMIR"

REPORT Wln.

No. 3893

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The WELLINGTON Surveyor reports (4.45)  
 this 4 masted barque placed in floating dock, bottom  
 coated, shell plating drilled where considered necessary,  
 repairs to deck plating in way of galley and to minor  
 items effected.  
 On account of heavy weather damage, 18 new sails supplied.

It is submitted the vessel is eligible to  
 remain as classed with record of survey 4.45.

4.45 Wln.

SHELL PLATING TO BE DRILLED  
 WHEN VESSEL IS 43 YEARS OLD



© 2018

Lloyd's Register  
 Foundation