

1m.8.27.

25 OCT 1927

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Stl.4 Mat.Bk."PASSAT". Rpt. Ham. No. 17672.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.)

Nature of Survey _____

The Hamburg Surveyors report this vessel placed in dry dock, the bottom cleaned and coated.


The poop has been lengthened and the after peak converted into a water ballast tank.

It is submitted the vessel appears worthy to remain as classed, with record of survey 10,27, as recommended.

100A1.
10,27.Ham.

Amend P 18'
to P 53'

Insert A.P.T 29t.



24. 10. 27.



© 2018

Lloyd's Register
Foundation