

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, Rec'd 12th JUNE, 1883.)

No. 5319

No. in Survey held at Reg. Book.

Date, first Survey 23rd Dec. 82 Last Survey 23rd May 1883

on the Hull & Lyle Steamer "Amie"

(No. of Visits)

Master

YEAR

MONTH

Tonnage under Tonnage Deck

Ditto of Spar Deck, or Awaiting Deck

Ditto of Poop

Ditto of Raised Or. Deck

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rules

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as S^r mer, cut on Bm.

Built at

When built

Owners

Port belonging to

Residence

By whom built

Destined Voyage

If Surveyed Afloat or in Dry Dock

(State Name of Dock)

Length of Poop

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

Port

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Through damage

Classed

2. 8. 81

2. 8. 81

Placed on blocks on Slip-way and the hull and bottom; then these plates on Starboard side in after hold removed of steel the Pultruss and Rail on Starboard side, in midships for about 40 feet in length. Bridge deck and Rails repaired

Not damage. The cementing and floors, under new Boiler made good; the decks in way of Boiler hatch pair renewed and decks re-caulked. Boiler hatch Comings repaired and the hull cleaned and painted

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Good

Good

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper (or Y.M.)

When put on

Caulking of

Bottom, Deck, & Waterways

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

The Amount of Entry Fee ...

Special

Certificate (if required)

to be sent as per margin...

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

FRIDAY 15 JUNE 1883

18

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2018

Lloyd's Register Foundation