

IRON 11977

No. 352 Survey held at London Date Oct 20th 1873
 on the Iron Screw Steamer Charles Howard Master Cunham
 Tonnage 1304 Built at Sunderland When built 1866
 By whom built 1021 Pile Owners Ryde & Co
 Port belonging to London Destined Voyage River Plate
 If Surveyed Afloat or in Dry Dock Mill Wall dry dock

Last Survey, No. 11633 Port of London Classed 90. A. 1. S.S. 114 76

The present Condition of the

Decks	<u>good</u>	Treenails	<u>Rivets</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	<u>Timbers of the Frame at the Openings</u>	<u>"</u>	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>	<u>"</u>	Sails	<u>"</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	<u>"</u>	Anchors, No. of <u>3 P, 1 S, 2 L</u>	<u>"</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	<u>"</u>	Cables	<u>"</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	<u>"</u>	Hawsers and Warps	<u>"</u>
Wales	<u>"</u>	Rudder <u>efficient</u>	<u>"</u>	<u>"</u>	Standing and Running Rigging	<u>"</u>
Plank (Bottom) and Counter	<u>"</u>	Copper	<u>When put on</u>	<u>"</u>		

General Observations and Opinion,

Cleaned the bottom, overhauled the caulking of batts. and recoated her outside. - Neither has this vessel any deadlights fitted over the top^d Room skylight pointed out the same, and wrote the Owners respecting both vessels. - (See Copy of letter) Sam of opinion. She is entitled to remain as classed 90. A. 1.

Committee's Minute 21st Oct 1873

Character assigned 90 A 1

Certificate (if required).