

REPORT of SURVEY for REPAIRS, &c.

No. 12493

No. in Survey held at *Sunderland*

Date, first Survey *17th Sept*

(Received at London Office, *27/9/80*)
Last Survey *Sep^r 23rd 1880*

Reg. Book.

581 on the *S.S. "Charles Howard"*

Master *W. Chater*

TONNAGE under Tonnage Deck

Ditto of Spar Deck, or Aweighing Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, as on Beam

Engine Room

Reg. Tons as St. Mer, cut on Bm.

Built at *Sunderland*

When built *1866*

MONTH.

Owners *Wm Briggs & Son* Port belonging to *Sunderland*

Residence *Lawson Street Sunderland*

By whom built *W Pile*

Destined Voyage *Aden*

If Surveyed Afloat or in Dry Dock *South Dock afloat*

(State Name of Dock)

Length of Poop

ft. Ditto, Forecastle

ft. Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No. *12,270*

Port *Sunderland*

Classed

90.A.1

REPAIRS, OR EXAMINATION AS PER RULE

Annual

Cause of Repairs to be clearly stated.

S. P. 8-77

In contact with the Quay; removed three plates on the Port Bow, two of which were renewed and one refitted

Renewed the small Kedge Anchor weighing *2.0.7* tested to *4.12.2.0* at R.N.C.P.Y by *J. Hartwell* dated *20th Sep^r 1880*; Certificate *N. 864*

Present Condition of the

Decks

good

Waterways

Treenails

good

Breasthooks and Stenson

Windlass and Capstan

good

Comings

Transoms, Pointers, and Crutches

Pumps

Upper Deck Beams & Fastenings

~~Timber~~ of the Frame at the openings

Boats *4*

Lower Deck Beams & Fastenings

Ditto Ditto at other places

Masts, Yards, &c.

Planksheers

Keelsons

Condition, how ascertained *from (B.R.)*

Sheerstrakes

Clamps and Shells

Sails

Topsides

Ceiling

Anchors No. of *3 B. 18. 2 K* *good*

Wales

Rudder

Cables

~~Blank~~ (Bottom) and Counter

Copper (or Y.M.)

When put on

Hawsers and Warps

Engine Room Skylights

Caulking of

Standing & Running Rigging

General Observations, Opinion as to Class, &c.

Bottom, Deck, & Waterways

Cargo and Main Hatchway

Coal Bunker, Openings, Lids, &c.

Scuppers

Hatches

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

The Amount of Entry Fee£

received by me,

Special£

21st Sept 1880

Certificate (if required)

AW

to be sent as per margin...

£ - : 5 : -

(Travelling Expenses, if any, £ *nil*)

Committee's Minute

Tuesday, September, 28th 1880,

Character assigned

90.A.1

TRW

Joseph Keen

Surveyor to Lloyd's Register of British and Foreign Shipping.