

ANNUAL SURVEYS.

No. in Reg. Book. 526 No. 1250 Survey held at Honkoo Date, first Survey 25 Jan Last Survey 27 June 1877
 on the "P. O. Medicine" Master Whitson
 Tonnage 1320 Built at P. Glasgow When built 1874 3rd
 By whom built Duncan Owners Albion S. Co
 Port belonging to Glasgow Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Linekin Dock

Last Survey, No. 13889 Port of Iron

Classed

Years assigned.

Character in Register Book.

100 A

2.75

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Freeboards Paint when seen Good

Breasthooks and Stemson de de

Transoms, Pointers, and Crutches de de

Timbers of the Frame at the Openings de de

Ditto ditto at other places de de

Keelsons de de

Clamps and Shelves de de

Ceiling de de

Rudder de de

Copper on Y.M. When put on _____

Caulking of Bottom, Deck, & Waterways de

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchor, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Cargo and Main Hatchways

Hatches

Bottom coated. This vessel appears
eligible to remain as classed.

Surveys with ballast in hold

Committee's Minute

10th July, 1877.

Character assigned

100 A

TPW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)



© 2018

Lloyd's Register Foundation