

## ANNUAL SURVEYS.

No. 5152 Survey held at Glasgow Date, first Survey 5 Aug. Last Survey 5 Aug. 1880  
 No. in on the S. Durnedin Master J. Whitson  
 Reg. Book. 534 Tonnage 1250 Built at Port Glasgow When built 1874 - 3mo.  
 By whom built Duncan Owners Albion Shipping Co.  
 Port belonging to Glasgow Destined Voyage Durnedin  
 If Surveyed Afloat or in Dry Dock Govan dry dock

Last Survey, No. 24170 Port of Iron

Present Condition of the  
Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

good ~~Keels~~ ribs

Breasthooks and Stems

Transoms, ~~Painters~~, and Crutches

~~Timbers~~ of the Frame at the Openings

~~Ditto~~ ditto at other places

Keelsons

~~Clamp~~ and ~~Stays~~

Ceiling

Rudder

Copper ~~or~~ P.M.

When put on

Caulking of

Bottom, Deck, & Waterways

Coal Bunker, Openings, Lids, &c.

Scuppers

Classed

Years assigned

Character in Register Book

100 A. 1.

S. S. Lon. N<sup>o</sup> 1 - '78.

8.77

Windlass and Capstan

Pumps

Boats 6.5.0

Masts, Yards, &c.

Condition, how ascertained from deck

Sails said to be good & sufficient

Anchors, No. of 3 B. 1 B. 2 H.

Cables said to be complete

Hawsers and Warps

Standing and Running Rigging

Cargo and Main Hatchways good Hatches good.

This vessel's bottom has now been cleaned and coated with  
Baird's composition.

She is now, in my opinion, in good condition and eligible  
to remain as classed.

Committee's Minute

Friday, August 20th. 1880

Character assigned

100 A. 1

Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required)



© 2018

Lloyd's Register  
Foundation