

ANNUAL SURVEYS. 26012

No. 29966 Survey held at London Date, first Survey Feb 10th Last Survey Feb 18th 1880
 No. in on the SS Shattlevan Master C Pearson
 Reg. Book. 1144 Tonnage 1588 Built at Pt Glasgow When built 1875 HM
 By whom built Blackburn Owners Burnell & Co
 Port belonging to Glasgow Destined Voyage China
 If Surveyed Afloat or in Dry Dock Harbour for Wks Dry Stk

Last Survey, No. 2580 Port of Dron
 Condition of the Good

Classed 100A-5.75
 Years assigned. SS Lin M-179
 Character in Register Book.

Trunnels <u>Good</u>	Treenails <u>Good</u>	Breasthooks and Stemson <u>Good</u>	Windlass and Capstan <u>Good</u>
Comings <u>Good</u>	Transoms, Pointers, and Crutches <u>Good</u>	Timbers of the Frame at the Openings <u>Good</u>	Pumps <u>Good</u>
Deck Beams & Fastenings <u>Good</u>	Ditto ditto at other places <u>Good</u>	Keelsons <u>Good</u>	Boats <u>Good</u>
Deck Beams & Fastenings <u>Good</u>	Clamps and Shelves <u>Good</u>	Ceiling <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Plank sheers <u>Good</u>	Rudder <u>Pushed & also Rint renewed</u>	Copper or Y.M. <u>Good</u>	Condition, how ascertained <u>Good</u>
Sheerstrakes <u>Good</u>	Caulking of <u>Good</u>	Bottom, Deck, & Waterways <u>Good</u>	Sails <u>Good</u>
Topsides <u>Good</u>	Coal Bunker, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	Anchors, No. of <u>3 Bns. St & 9 Bids</u>
Wales <u>Good</u>	General Observations, Opinion as to Class, &c. <u>Well maintained</u>	Cargo and Main Hatchways <u>Good</u>	Cables <u>Good</u>
Plank (Bottom) and Counter <u>Good</u>		Hatches <u>Good</u>	Hawsers and Warps <u>Good</u>
Engine Room Skylights <u>Good</u>			Standing and Running Rigging <u>Good</u>

She is now in good condition and eligible to remain as classed.

Committee's Minute Tuesday, March, 16th 1880.

Character assigned 100A

Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

No. Survey held at Date, first Survey Last Survey 1880
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Years assigned. Character in Register Book.

Present Condition of the	Treenails	Windlass and Capstan
Decks	Breasthooks and Stemson	Pumps
Waterways	Transoms, Pointers, and Crutches	Boats
Comings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Upper Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shelves	Anchors, No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper or Y.M. When put on	Standing and Running Rigging
Plank (Bottom) and Counter	Caulking of	
Engine Room Skylights	Bottom, Deck, & Waterways	
Coal Bunkers, Openings, Lids, &c.	Scuppers	
General Observations, Opinion as to Class, &c.	Cargo and Main Hatchways	
	Hatches	

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18