

ANNUAL SURVEYS.

No. 1128 Survey held at London Date, first Survey 7 Last Survey 4 July 1881
 No. in on the Iron S.S. "Shuttleworth" Master C Pearson
 Reg. Book. 1128 Net 1588 Built at Port Glasgow When built 1875 Year 11 Month 11
 Tonnage Gross 2436 Under Dk. 2257 By whom built Purcell & Co Owners Purcell & Co
 Port belonging to Glasgow Destined Voyage China & Japan
 If Surveyed Afloat or in Dry Dock West India dry Dock (State Name of Dock.)

Last Survey, No. 26012 Port of Iron Classed 100A1 280
 Present Condition of the Decks Good Treenails Good Breasthooks and Stems Good
 Waterways Good Transoms, Pointers, and Crutches Good Windlass and Capstan Good
 Comings Good Timbers of the Frame at the Openings Good Pumps Good
 Upper Deck Beams & Fastenings Good Ditto ditto at other places Good Boats Good
 Lower Deck Beams & Fastenings Good Keelsons Good Masts, Yards, &c. Good
 Planksheers Good Clamps and Shells Good Condition, how ascertained from Deck
 Sheerstrakes Good Ceiling Good Sails Good
 Topsides Good Rudder Good Anchors, No. of 3 B. 15 L. 1 K
 Wales Good Copper or Y.M. When put on 1875 Cables Good
 Plank (Bottom) and Counter Good Caulking of Bottom, Deck, & Waterways Good Haucers and Warps Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Standing and Running Rigging Good
 (If a Steam Ship, state if a Report is also sent on the Machinery No)
 General Observations, Opinion as to Class, &c. Good Cargo and Main Hatchways Good Hatches Good

Bottom repainted. She appears good and firm and eligible in my opinion to continue as classed

Committee's Minute Tue day, July, 26th 1881. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Character assigned 100A Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Net Built at When built Year Month
 Tonnage Gross Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of Classed
 Present Condition of the Decks Treenails Breasthooks and Stems
 Waterways Transoms, Pointers, and Crutches Windlass and Capstan
 Comings Timbers of the Frame at the Openings Pumps
 Upper Deck Beams & Fastenings Ditto ditto at other places Boats
 Lower Deck Beams & Fastenings Keelsons Masts, Yards, &c.
 Planksheers Clamps and Shells Condition, how ascertained
 Sheerstrakes Ceiling Sails
 Topsides Rudder Anchors, No. of
 Wales Copper or Y.M. When put on Cables
 Plank (Bottom) and Counter Caulking of Bottom, Deck, & Waterways Haucers and Warps
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c. Hatches

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



© 2018 Lloyd's Register Foundation