

NAME OF VESSEL....."THISTLEGORM".....

Extract from freeboard verification of marking form received
from theSUNDERLAND..... Surveyors dated the
.11.6.40.....

| | | | |
|--|----|---------------------|--------|
| Moulded depth | 27 | ft. 10 | ins. ✓ |
| Corresponding draught | 25 | ft. 0 | ins. ✓ |
| Moulded depth as shewn on draught sheet | 27 | ft. 10 | ins. ✓ |
| Tropical freeboard | 2 | ft. 6 $\frac{1}{4}$ | ins. ✓ |
| Summer " | 3 | ft. 0 $\frac{1}{2}$ | ins. ✓ |
| Winter " | 3 | ft. 6 $\frac{3}{4}$ | ins. ✓ |
| W.N.A. " | - | ft. - | ins. ✓ |
| Fresh Water Allowance | | 6 $\frac{1}{2}$ | ins. ✓ |

Marked from ~~wood~~ steel upper deck.

Checked by.....*jm*.....
Date.....8.7.40.....



© 2018

Lloyd's Register
Foundation