

3920

## REPORT of SURVEY for REPAIRS.

Change of Owners and Change of Name

No. in Reg. Book. **No. 19159** Survey held at **Liverpool** Date **Nov. 2<sup>nd</sup>** 18**64**  
 on the **Iron Brigitta** { **Lat. Lancashire** } Master **Scott**  
 Tonnage **270** Built at **Garston** When built **1863**  
 By whom built **Garston S. B. Co.** Owners **W. Ling in der.**  
 Port belonging to **Liverpool** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Canning Dry Dock**

Last Survey, No. **3399** Port **Iron.** Classed **B1.**  
 REPAIRS **None done.** **Bottom scraped and painted.**

## Present Condition of the

Decks <b>Good</b>	Treenails	Windlass and Capstan <b>Good</b>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats <b>Good and sufficient</b>
Upper Deck Beams & Fastenings <b>Iron</b>	Timbers of the Frame at the openings <b>Iron</b>	Masts, Yards, &c. <b>Good</b>
Lower Deck Beams & Fastenings <b>Good</b>	Ditto Ditto at other places <b>Good</b>	Sails
Plank-sheers <b>Where</b>	Keelsons <b>Where</b>	Anchors No. of
Beerstrakes <b>See</b>	Clamps and Shelves <b>See</b>	Cables
Sides	Ceiling	Hawsers and Warps
Staves	Rudder	Standing & Running Rigging
Hulk (Bottom) and Counter	Copper When put on	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <b>Good where examined.</b>	

This vessel is now in good condition and eligible  
 in my opinion to remain as classed **B1.**

Amount of Fee.....£ 1 : " : " is received by me,

Special..... " : " : " 11/65-RM

Certificate (if required) " : " : "

Committee's Minute **Liverpool 17<sup>th</sup> January 1865**

Character assigned **B1**

GR

J. F. R. Light.



Index - 19189