

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 19401** Survey held at **Burtonhead** Date **Oct 24** 18 **65**  
 on the **Bt. "Ada"** Master **R Griffiths**  
 Tonnage **210** Built at **Garston** When built **1843**  
 By whom built \_\_\_\_\_ Owners **J & P. Johnson**  
 Port belonging to **Liverpool** Destined Voyage **Bio Grande**  
 If Surveyed Afloat or in Dry Dock **Great Float graving dock**

Last Survey, No. **3920** Port **Wm.** Classed **B 1**

## REPAIRS

The bottom scraped clean & coated with composition

### Present Condition of the

Decks	good	Trunnels	rosts	good	Windlass and Capstan	good & sufficient
Waterways	"	Breasthooks and Stemson			Pumps	"
Comings	"	Transoms, Pointers, and Crutches			Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"		Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"		Condition, how ascertained	"
Planksheers	"	Keelsons	"		Sails	"
Sheerstrakes	"	Clamps and Shelves	"		Anchors No. of	"
Topsides	"	Ceiling	"		Cables	"
Wales	"	Rudder	"		Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	When put on		Standing & Running Rigging	"

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. **Satisfactory**

Is now in an efficient condition and in my opinion should remain as Classed.

The Amount of Fee.....£ 1 : : : is received by me.

Special..... : : : 16/4/65

Certificate (& required) : : : 5 : :

Committee's Minute **Liverpool, 19<sup>th</sup> December 1865**

Character assigned **B 1** Record Owners



