

8508 ANNUAL SURVEYS.

Rec'd 8/12/70

No. 3440 Survey held at Glasgow Date Nov. 14 1870
 on the Iron Ship "Agnes Muir" Master J. Anderson
 Tonnage 857 Built at Port Glasgow When built 1869
 By whom built Duncan Owners Henderson & Co.
 Port belonging to Glasgow Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Tod & Mc Gregor's Slip.

Last Survey, No. 6962 Port of Glasgow

Classed

* A 1
3.69

The present Condition of the

Decks <u>good</u>	Transoms <u>Rivets</u> <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>✓</u>	Breasthooks and Stemson <u>✓</u>	Pumps <u>✓</u>
Comings <u>✓</u>	Transoms, Pointers, and Crutches <u>✓</u>	Boats <u>✓</u>
Upper Deck Beams & Fastenings <u>✓</u>	Timbers of the Frame <u>at the Openings</u> <u>✓</u>	Masts, Yards, &c. <u>✓</u>
Lower Deck Beams & Fastenings <u>✓</u>	Do Do <u>at other places</u> <u>✓</u>	Sails <u>and</u>
Planksheers <u>✓</u>	Keelsons <u>✓</u>	Anchors No. of <u>3 B 1 S 2 K</u>
Sheerstrakes <u>✓</u>	Clamps and Shelves <u>✓</u>	Cables <u>✓</u>
Topsides <u>✓</u>	Ceiling <u>✓</u>	Hawsers and Warps <u>efficient</u>
Wales <u>✓</u>	Rudder <u>✓</u>	Standing & Running Rigging <u>✓</u>
Plank (Bottom) and Counter <u>✓</u>	Copper <u>sement</u> When put on <u>1869</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

now done, The bottom cleaned and painted -
She is now in good condition, fit in my
opinion to remain, as classed * A 1

Committee's Minute 9th December 70

Character assigned A 1

J. D. Smith
 Certificate (if required)