

No.

Survey held at

10478
London

Date

Aug 6th 17th 1872

on the

Iron Ship "Agnes Muir"

Master

J. Anderson

Tonnage

867

Built at

P. Glasgow

When built

1869

3 m

By whom built

Duncan

Owners

J. Henderson & Co

Port belonging to

Glasgow

Destined Voyage

Auckland

If Surveyed Afloat or in Dry Dock

Ratcliff Dry Dock & East India Dock

Last Survey, No.

8508

Port of

Iron.

Classed

*A. 1.

11.70

The present Condition of the

Decks

good

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

where

Planksheers

painted

Sheerstrakes

Topsides

seen

Wales

Plank (Bottom) and Counter

scraped & painted

Rivets

Rivets

good

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

where

Keelsons

Clamps and Shelves

Ceiling new in the flat

seen

Rudder

Copper Cement When put on 1869

Windlass and Capstan

good

Pumps

Boats

Masts, Yards, &c.

Sails

where

Anchors, No. of 3B. 1S. 2K

Cables

Hawsers and Warps

seen

Standing and Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good where seen

Now done, Bottom cleaned and painted, the ceiling in the flat (within the side intercostals) with American Rock Elm, the floors scraped and painted and the cement repaired. She is now in good and efficient condition. It is my opinion to remain as classed.

Committee's Minute

3rd September 1872

Character assigned

*A. 1.

J. B. W.

J. Morrison -
Certificate (if required).