

ANNUAL SURVEYS.

16819
Recd. 21.7.75

No. in Reg. Book. **No.** 228 Survey held at **London** Date, first Survey **July 15 1875** Last Survey **July 15 1875**
on the **S Agnes Muir** Master **Jac. Lowe**
Tonnage **861** Built at **Glasgow** When built **1865** 3 M.
By whom built **Duncan** Owners **Killick Martin & Co.**
Port belonging to **London** Destined Voyage
If Surveyed Afloat or in Dry Dock **Dry Dock**

Last Survey, No. **13162** Port of **Gron.** Classed **2A1** 7.76
Present Condition of the Decks **Good** **Treenails** **Good**
Waterways **Good** Breasthooks and Stemson **Good**
Comings **Good** Transoms, Pointers, and Crutches **Good**
Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good**
Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good**
Planksheers **Good** Keelsons **Good**
Sheerstrakes **Good** Clamps and Shelves **Good**
Topsides **Good** Ceiling **Good**
Wales **Good** Rudder **Good**
Plank (Bottom) and Counter **Good** Copper or Y.M. Painted When put on **Now**
Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
General Observations, Opinion as to Class, &c.

At present the bottom scraped Painted & Grated
She is now in an efficient state of repair
and entitled to remain as Classed

Committee's Minute **27th July 1875** **Senhouse Martindeale**
Character assigned **2A1** **DB**
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

No. in Reg. Book. **No.** 69 Survey held at **London** Date, first Survey **June 25 1875** Last Survey **June 25 1875**
on the **S Zealandia** Master
Tonnage **1116** Built at **Glasgow** When built **1865** 6 m.
By whom built **228** Owners **Shaw Savill & Co.**
Port belonging to **London** Destined Voyage
If Surveyed Afloat or in Dry Dock **Dry Dock**

Last Survey, No. **12915** Port of **Gron** Classed **2A1** 6.76
Present Condition of the Decks **Good** **Treenails** **Good**
Waterways **Good** Breasthooks and Stemson **Good**
Comings **Good** Transoms, Pointers, and Crutches **Good**
Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good**
Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good**
Planksheers **Good** Keelsons **Good**
Sheerstrakes **Good** Clamps and Shelves **Good**
Topsides **Good** Ceiling **Good**
Wales **Good** Rudder **Good**
Plank (Bottom) and Counter **Good** Copper or Y.M. Painted When put on **Now**
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
General Observations, Opinion as to Class, &c.

At present the bottom scraped Painted & Grated
She is now in an efficient state of repair
and entitled to remain as Classed

Committee's Minute **27th July 1875** **Senhouse Martindeale**
Character assigned **2A1** **DB**
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18