

ANNUAL SURVEYS.

Rev 21/8/76

Book Number 443. No. 25. Survey held at Copenhagen (Sweden) Dates 13-14th August 1876
 on the S.S. Ship the Raaff Master G. Fleischer
 Tonnage 794 Built at Copenhagen When built 1870 6 mcs.
 By whom built Messrs. Burmeister & Co Owners Steamcompany Denmark
 Port belonging to Copenhagen Destined Voyage Baltic & England
 If Surveyed Afloat or in Dry Dock on a patent Slip at Malmo High and Black

Last Survey, No. 14601 Port of London June 1875 Classed 90 A-1-
 The present Condition of the Steamship Raaff is now good as ever S.S. No. 75

Decks	Treenails	Windlass and Capstan
Waterways <u>All</u>	Breasthooks and Stemson <u>All</u>	Pumps <u>All</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>very</u>
Upper Deck Beams & Fastenings <u>very</u>	Timbers of the Frame at the Openings <u>very</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails <u>Good</u>
Planksheers	Keelsons <u>Good</u>	Anchors, No. of <u>3 Heavy 2 Light 2 Kops</u>
Sheerstrakes <u>Good</u>	Clamps and Shelves	Cables <u>195 ft. 1 1/4 - 1 3/8 inch</u>
Topsides	Ceiling	Hawsers and Warps <u>all good and enough</u>
Wales	Rudder	Standing and Running Rigging <u>Good</u>
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways
The Raaff Steamer, went over to Malmo in purpose on the new Slip here to put in a new Propeller shaft, and also to benefit engine and boilers by overhauling and refitting. The Ceiling taken up and new cement and paint laid on bottom and sides. Outriggers wholly scraped and 3 coats of paint put on. The ship is now in a fit state to carry any number of goods to any part of the world.
 Committee's Minute 1876

Character assigned 90 A-1- JKW
 Charges: Entry £1 9 0 Survey 1 9 0 Travelling 5 9 0 Certified 5 9 0 Returned £3 6 0
 Certificate (if required). M. J. Loring

No. Survey held at Date 18
 on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 Surveyed Afloat or in Dry Dock

Survey, No. Port of Classed
 Condition of the
 Treenails
 Breasthooks
 Transoms, 4 Tan Crutches
 Timbers of the Frame at the Openings
 Ditto at other places
 Keelsons
 Clamps
 Ceiling
 Rudder
 Copper When put on
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Sails
 Anchors, No. of
 Cables
 Hawsers and Warps
 Standing and Running Rigging
 General Observations and Opinion, Deck, and Waterways
 Committee's Minute
 Character assigned
 Certificate (if required).