

No. 568

Survey held at

Hastings

Date

1 July

1879.

on the

S.S. 'Hoff'

Master

G. Fleischer

Tonnage

794  
1103

Built at

Copenhagen

When built

1870 - 6 mdy.

By whom built

Bureauisten

Owners

Hans. Sels. &amp; Danmark

Port belonging to

Copenhagen

Destined Voyage

Hastings

If Surveyed Afloat or in Dry Dock

in dry dock

Last Survey, No.

Port of

Classed

90 A. 1.

S.S. No. 55 638

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams &amp; Fastenings

Lower Deck Beams &amp; Fastenings

Planks

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &amp;c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing &amp; Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

This vessel was placed in dry dock for the purpose of getting bottoms scraped and repainted. I informed the Master that his ship was due for S.S. No. 2. his reply was, that he was aware of it; as the Vessels were already informed through the Copenhagen Surveyors; but they resolved not to do anything as the Committee's Minute 4th July, 1879. This was also classed in Whites and that this class was all they cared about & quiet ship.

Character assigned

Deferred

Certificate (if required). no

Reply from

Report sent to the Society 13th July 1879