

40929

No. in on the SS Orient Master W. J. Benson
Reg. Book. 346 Year. 3 Month.

Under Dk. 5718	By whom built	Alder	Owners	Orient Steam Nav Co
Port belonging to	Glasgow	Destined	Voyage	Australia

Last Survey, No. <u>44046</u>		Port of <u>Long</u>	Classed <u>1</u>	Years assigned. <u>1</u>	Character in Register Book.
-------------------------------	--	---------------------	------------------	--------------------------	-----------------------------

Waterways _____

<i>Upper Deck Beams & Fastenings</i>	"	Ditto	ditto	at other places	"	Boats	"
<i>Lower Deck Beams & Fastenings</i>	"						

Sheerstrakes _____ " Ceiling _____ " Sails _____ Good
Topsides _____ Rudder _____ Anchors, No. of 3 No. 12 & 14 lbs

Plank (Bottom) and Counter	"	Caulking of Bottom, Deck, & Waterways	Good	Raisers and Warps	"
Engine Room Skylight	"			Standing and Running Rigging	"

She is now in an efficient state

Symouse Martindale

Character assigned *100 B 1111* Surveyor to Lloyd's Register of British and Foreign Shipping.

No.	Survey held at	Date, first Survey	Last Survey	18

Tonnage } ^{Net} _____ Built at _____ When built _____
 } ^{Gross} _____ By whom built _____ Owners _____

If Surveyed Afloat or in Dry Dock

Present Condition of the Decks	Treenails
-----------------------------------	-----------

Comings _____
 Lower Deck Beams & Fastenings _____
 Transoms, Pointers, and Crutches _____
 Timbers of the Frame at the Openings _____
 Pumps _____
 Reefs _____

Planksheers	Clamps and Shells	Condition, how ascertained
St.	Ceilings	Sails

<i>Wales</i> _____	<i>Copper or Y.M.</i> _____	<i>When put on</i> _____	<i>Cables</i> _____
	<i>Caulking of</i> _____		<i>Hawsers and Warps</i> _____

If a Steam Ship, state if a Report is also sent on the Machinery)
General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ *18* _____

Certificate (if required, to be sent as per margin) Paid 18

