

ANNUAL SURVEYS.

No. 42281 Survey held at London Date, first Survey 16 Feb'y Last Survey 21st Feb'y 1883
 No. in on the SS Orient Master W. F. Hewison
 Reg. Book. 210 Net 3440 Built at Glasgow When built 1879
 Tonnage Gross 5386 By whom built J. Elder & Co. Owners Orient Steam Navigation Co.
 Under Dk. 5118 Port belonging to Glasgow Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Albert by S. K. & Afloat (State Name of Dock.)

Last Survey, No. 41829 Port of Lon.

Classed 100 A1 Years assigned 9.82 Character in Register Book.

Present Condition of the Decks Good Treennails Good Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Good When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom & counter
She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, 2nd Mar 1883.

Character assigned 100 A1

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in on the Master
 Reg. Book. Net Built at When built
 Tonnage Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No.

Port of

Classed

Years assigned Character in Register Book.

Present Condition of the Decks Treennails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

ANNUAL SURVEY

1890

Name of Survey		Date of Survey		Name of Surveyor		Name of Owner		Name of Agent or in Charge	
1. Name of Survey		2. Date of Survey		3. Name of Surveyor		4. Name of Owner		5. Name of Agent or in Charge	
6. Description of Survey		7. Description of Survey		8. Description of Survey		9. Description of Survey		10. Description of Survey	
11. Description of Survey		12. Description of Survey		13. Description of Survey		14. Description of Survey		15. Description of Survey	
16. Description of Survey		17. Description of Survey		18. Description of Survey		19. Description of Survey		20. Description of Survey	
21. Description of Survey		22. Description of Survey		23. Description of Survey		24. Description of Survey		25. Description of Survey	
26. Description of Survey		27. Description of Survey		28. Description of Survey		29. Description of Survey		30. Description of Survey	
31. Description of Survey		32. Description of Survey		33. Description of Survey		34. Description of Survey		35. Description of Survey	
36. Description of Survey		37. Description of Survey		38. Description of Survey		39. Description of Survey		40. Description of Survey	
41. Description of Survey		42. Description of Survey		43. Description of Survey		44. Description of Survey		45. Description of Survey	
46. Description of Survey		47. Description of Survey		48. Description of Survey		49. Description of Survey		50. Description of Survey	
51. Description of Survey		52. Description of Survey		53. Description of Survey		54. Description of Survey		55. Description of Survey	
56. Description of Survey		57. Description of Survey		58. Description of Survey		59. Description of Survey		60. Description of Survey	
61. Description of Survey		62. Description of Survey		63. Description of Survey		64. Description of Survey		65. Description of Survey	
66. Description of Survey		67. Description of Survey		68. Description of Survey		69. Description of Survey		70. Description of Survey	
71. Description of Survey		72. Description of Survey		73. Description of Survey		74. Description of Survey		75. Description of Survey	
76. Description of Survey		77. Description of Survey		78. Description of Survey		79. Description of Survey		80. Description of Survey	
81. Description of Survey		82. Description of Survey		83. Description of Survey		84. Description of Survey		85. Description of Survey	
86. Description of Survey		87. Description of Survey		88. Description of Survey		89. Description of Survey		90. Description of Survey	
91. Description of Survey		92. Description of Survey		93. Description of Survey		94. Description of Survey		95. Description of Survey	
96. Description of Survey		97. Description of Survey		98. Description of Survey		99. Description of Survey		100. Description of Survey	