

ANNUAL SURVEYS.

41021

No. 472 Survey held at London Date, first Survey Dec 13 Last Survey Dec 22 1887
 No. in on the SS Glenfuirt Master J. Hogg
 Reg. Book. 472 Net 2476 1936 Built at Glasgow When built 1880 Month. 11
 Tonnage Gross 2585 Under Dk. 708 2696 By whom built Len & Glas Co Owners McGregor Gov & Co
 Port belonging to Glasgow Destined Voyage China
 If Surveyed Afloat or in Dry Dock greens by the & afloat

Last Survey, No. 5277 Port of Gls Classed 100A1 1881

Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Boated When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom & counter

She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, December 3rd, 1881. Senhouse Martindale
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Net Built at When built Year. Month.
 Tonnage Gross Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of Classed

Present Condition of the Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18