

ANNUAL SURVEYS.

43432

23 1884

No. 407 Survey held at London Date, first Survey 24th Last Survey 28th Jan'y, 1884
 No. in Reg. Book. on the P. S. "Glenfruin" Master E. J. Norman
 Net 1936 Built at Glasgow When built 1880 11
 Gross 2985 By whom built Mr. Glasgow & Co. Ltd. Owners Mr. Geo. Gow & Co.
 Under Dk. 2696 Port belonging to Glasgow Destined Voyage Glasgow thence China
 If Surveyed Afloat or in Dry Dock Glasgow Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 112819 Port of London 8/83 Classed 100.A.1
 Present Condition of the Decks Good MOULDED DEPTH of Ship, if not yet recorded in Register Book Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shells do
 Topsides do Ceiling Good
 Rudder do
 Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Vessel placed in Dry Dock, bottom cleaned and painted

This vessel appears to be in good and efficient condition and in our opinion eligible to remain as classed.

Committee's Minute

Character assigned TRW

TUESDAY 5 FEB 1884

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Net Built at When built
 Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. Port of Classed

Present Condition of the Decks MOULDED DEPTH of Ship, if not yet recorded in Register Book
 Waterways Breasthooks and Stemson Windlass and Capstan
 Comings Transoms, Pointers, and Crutches Pumps
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings Boats
 Lower Deck Beams & Fastenings Ditto ditto at other places Masts, Yards, &c.
 Planksheers Keelsons Condition, how ascertained
 Sheerstrakes Clamps and Shells Sails
 Topsides Ceiling Anchors, No. of
 Wales Rudder Cables
 Plank (Bottom) and Counter Copper or Y.M. When put on Hawseers and Warps
 Engine Room Skylights Caulking of Bottom, Deck, & Waterways Standing and Running Rigging
 Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery...)

(Form No. 3 for Annual Survey, when there are no repairs, 4000-11/5/83.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)