

ANNUAL SURVEYS.

41880

No. _____ Survey held at London Date, first Survey 12th Oct^r Last Survey 12th Oct^r 1882No. in Reg. Book. on the Iron Steamer "Aberdeen" Master C. MathesonTonnage { Net 2371 Built at Glasgow When built 1881 12th Month.Gross 3616 By whom built R. Napier & Son Owners G. Thompson & CoUnder Dk. 2565 Port belonging to Aberdeen Destined Voyage AustraliaIf Surveyed Afloat or in Dry Dock A Royal Albert Dry Dock.Last Survey, No. 5619 Port of Ells Classed 100A.1.Present Condition of the Decks good Treennails good Rivets good Spar deck 2, 82Waterways D^o Breasthooks and Stemson D^oComings D^o Transoms, Pointers, and Crutches D^oUpper Deck Beams & Fastenings D^o Timbers of the Frame at the Openings D^oLower Deck Beams & Fastenings D^o Ditto ditto at other places D^oPlanksheers D^o Keelsons D^oSheerstrakes D^o Clamps and Shelves D^oTopsides D^o Ceiling D^oWales D^o Rudder D^oPlank (Bottom) and Counter D^o Copper or Y.M. When put onEngine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches goodGeneral Observations, Opinion as to Class, &c. The bottom has been examined & coated.This vessel appears to be in good & efficient condition & eligible to remain as classed.Committee's Minute Tuesday, 31st October, 1882Character assigned 100A.1 J. A. Truscott.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____

No. in Reg. Book. on the _____ Master _____

Tonnage { Net _____ Built at _____ When built _____ Year. _____ Month. _____

Gross _____ By whom built _____ Owners _____

Under Dk. _____ Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____

Present Condition of the Decks _____ Treennails _____

Waterways _____ Breasthooks and Stemson _____

Comings _____ Transoms, Pointers, and Crutches _____

Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____

Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____

Planksheers _____ Keelsons _____

Sheerstrakes _____ Clamps and Shelves _____

Topsides _____ Ceiling _____

Wales _____ Rudder _____

Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____

Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____

General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____

Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery.)

(Form No. 3 for Annual Survey, when there are no repairs. 4000-264/82.)

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)