

CPN. 335?

S.S. N<sup>o</sup> 2

## Report of Survey for Repairs of Engines and Boilers.

No. 35

No. in Reg. Book.

Survey held at

Antwerp

Date, first Survey

29<sup>th</sup> July

Last Survey

1<sup>st</sup> August 1879

449 on the

Iron S.S. Rolf

Master

G. Fleischer

Built at

Copenhagen

When built

1870

Tons

794  
1002

Owners

Steamship Co.  
Denmark

Port belonging to

Copenhagen

Classed

Years assigned.

Character in Register Book.

9041

Diameter of Cylinder (4) 21 and 42 inches

Length of Stroke

30 inches

Engines made at

Copenhagen

When made

YEAR.

1870

Pressure of Steam

50 lbs

Registered Horse Power

120

By whom made

Burmester

Particulars of Repairs and Examination of Cylinders, slide valves, pumps, Condenser, crank shaft, shafting and bearings as far as practicable the vessel being afloat; examined the boilers.

Found generally the working parts of the Engines in a very good state as well as the boilers which notwithstanding their age are in an exceptional state of preservation.

Some slight overhauling wanted were performed. I am of opinion that the Engines and boilers are now to the best of my knowledge in good and safe working condition.

The Amount of Fee ... £ 2 : 2 : 0 received by me,

Certificate (if required) ... £ : : 1<sup>st</sup> August 1879

Selling Expenses, if any, £

Committee's Minute

5th August,

1879.

Engineer Surveyor to Lloyd's Register of British &amp; Foreign Shipping.



Report of Survey for Repairs of Engines and Boilers

is eligible to have the additional  
to and 79 located in the  
Repaired Boilers  
Mullins 1/10/79