

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME *Steel Sc 3 Mst Sr "EMERALD"*

Report *Gls.* No. *48972*

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey *Damage & 2nd S.S. No. 3 & Alterations*

*2nd S.S. No. 3 has been held in lieu of 2nd S.S. No. 2 due 11.29.*

*Noted*

X The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

X

*W.H.*  
*14.3.29.*



© 2018

Lloyd's Register  
Foundation