

COPY

Ship's name "IONIA"Port

MSL

No.

13927

Class is subject toLast survey date

23.5.64

NONE

S.R.L. Appendix (as before or ~~none~~)Nature of present survey (afloat and in drydock)

Docking.

Recommendation

SUBMITTED record of DS 5,64 be assigned.

DS 5,64.

S.R.L. APPENDIX (AMENDED).

Forecastle deck bulwark plating etc. indented.

Promenade and boat deck bulwarks buckled (p s).

Bottom shell plating (p & s) scored.

B.5 (from aft) indented.

p.s. The Surveyors should be requested to state on
which side the damaged B.5 now reported is located.

shell plate



© 2018

Lloyd's Register
Foundation